


30X, 50X, 70X, 90X Safety And Operation Instructions



WARNING To Avoid Serious Injury And Ensure Best Results For Your Tapping Operation, Please Read Carefully *All* Operator And Safety Instructions Provided For This Tapping Unit as well as all other safety instructions that are applicable, especially those for your machine tool.

1. Proper Clothing: The rotating spindle of a machine tool can snag loose fitting clothing, jewelry or long hair. **Never** wear jewelry, long sleeves, neckties, gloves or anything else that could become caught when operating a machine tool. Long hair **must** be restrained or netted to prevent it from becoming entangled in rotating spindle.


2. Proper Eye Protection: Always wear safety glasses with side shields to protect your eyes from flying particles.



3. Proper Work Piece Fixturing: **Never** hold the work piece or the vise it is held in, by hand. The work piece **must** be clamped firmly to the table of the machine so that it cannot move, rotate or lift.

4. Proper Stop Arm / Torque Bar Installation For Self-Reversing Attachments On Conventional Machines:


Never extend the length of the standard stop arm supplied with your tapping attachment. A lengthened stop arm could break free, hitting the operator and causing serious injury.



Never hold the stop arm by hand. On reversal, full power of the machine is transmitted through the stop arm and the operator could be seriously injured.



Always mount a torque bar to hold the tapping attachment's stop arm from rotating. The torque bar **must** be mounted securely to the table or quill of your machine. The torque bar installation **must** be stronger than the largest tap in the capacity range of your tapping attachment. Order Tapmatic Torque Bars shown.



| Quill Clamp Capacity | Order No. | Max Tap Size | Torque Bar Assembly | Order No. | Max Tap Size |
|----------------------|-----------|--------------|------------------------|-----------|--------------|
| 1 1/2" - 2 3/8" | 29099 | 1/2" | Table Mount | 29097 | 3/4" |
| 2 3/8" - 4 1/2" | 290991 | 3/4" | Heavy Duty Table Mount | 29096 | 1 3/4" |

5. To Install Collets In Rubber-Flex Collet Chucks:

Some collets vary slightly in outside diameter. This does not affect capacity or performance. To install, put collet into the end of the drive spindle and push the tap chuck nut over it until the threads are engaged. Screw nut down completely. This will seat collet properly. Then back off nut to install tap. Collets must be ordered separately.

6. Inserting Tap In Rubber-Flex Collet Chucks:

Follow instructions to avoid excessive wear on back jaws when using tapping heads with collet chucks. Insert the tap into the tap chuck of the attachment so that the back jaws will engage the square of the tap. Hand tighten the chuck nut first, then tighten the back jaw on those units with adjustable back jaws. Then using the wrenches provided tighten the chuck nut firmly. When tightened correctly, the rubber flex collet should absorb most torque pressure, preventing the back jaws from being damaged by excessive torque. If the tap you are using has a male center at the square end, you must remove the point to assure maximum engagement in the back jaws.

| Rubber-Flex Collet | | | |
|--|-------------|--------------------|------------|
| For Use With Tapping Attachments With Rubber-Flex Collet Spindles. | | | |
| Collet Series | Catalog No. | Collet Range | |
| | | Tap Size | Shank Size |
| #21000 Series For 30X attachments with capacities (#0-1/4") | 21600 ★ | #0-#8 Standard | .098-.177 |
| | 21700 ★ | #10-1/4" Standard | .177-.256 |
| | 21500 | | .040-.098 |
| | 21200 | | .094-.146 |
| #22000 Series For 50X attachments with capacities (#6-1/2") | 22100 ★ | #0-1/4" Standard | .139-.257 |
| | 22200 ★ | 1/4"-1/2" Standard | .253-.383 |
| | 22300 | | .090-.180 |
| | 22000 | | .194-.318 |
| #24000 Series For 70X attachments with capacities (#10-5/8") | 24100 ★ | #10-1/2" Standard | .176-.383 |
| | 24000 ★ | 5/16"-5/8" | .280-.500 |
| | 24300 | | .110-.280 |
| #26000 Series For 90X attachments with capacities (1/2"-1-1/8") | 26100 | 1/2"-3/4" | .360-.630 |
| | 26200 | 7/8"-1-1/8" | .630-.900 |

30X, 50X, 70X, 90X Safety And Operation Instructions



WARNING To Avoid Serious Injury And Ensure Best Results For Your Tapping Operation, Please Read Carefully *All* operator and safety instructions provided for this tapping attachment as well as all other safety instructions that are applicable, especially those for your machine tool.

7. Continuous High Production Manual Tapping: Models for use on conventional drill press or milling machines. Speed is a critical factor in tapping. Please always refer to recommended tapping speed chart. Tapmatic Torque Control Reversing Tapping Attachments employ a planetary gear reversing mechanism that increases speed by a 1.75 x 1 ratio. This means that a machine speed of 2,000 RPM results in a reversing speed of 3,500 RPM. It is strongly recommended that you consider the **AVERAGE TAPPING SPEED** rather than machine speed when calculating your cycle time. For example, if machine speed is 1,500 RPM, reverse speed is 2,625 RPM, making your **AVERAGE TAPPING SPEED 2,062 RPM**. You must not exceed the maximum allowable speed marked on your tapping attachment.

8. Always Be Aware Of The Potential Hazards Of A Machining Operation: Sometimes working with your machine can seem routine. You may find that you are no longer concentrating on the operation. A feeling of false security can lead to serious injury. **Always** be alert to the dangers of the machines with which you work. **Always** keep hands, body parts, clothing, jewelry and hair out of the areas of operation, when the machine spindle is rotating. Areas of operation include the immediate point of machining and all transmission components including the tapping attachment. **Never** bring your hand, other body parts or anything attached to your body into any of these areas until the machine spindle is completely stopped.

9. Be aware of any other applicable safety instructions / requirements.

10. The tapping attachment housing, drive spindle and tap itself can become hot to the touch after operation. Use caution when removing the attachment from the machine or handling.

Check List For Good Tapping

- !**
- 1. **Never** use this unit before reading all safety instructions for this attachment as well as the machine it is to be used on.
 - 2. Is tap sharp and of correct design for current job?
 - 3. Is tap in proper alignment with drilled hole?
 - 4. Is machine speed correct?
 - 5. Is machine feed correct?
 - 5. Is machine stop set properly so tap releases in neutral rather than bottoming in work piece or fixture?
 - 6. Is work piece held rigidly against rotation and upward movement?
 - 7. Is drilled hole the correct size?
 - 8. Is clearance between the drilled hole and tap sufficient at start position to allow the tap to clear the hole upon retraction?
 - 9. Is the stop arm of the tapping attachment held rigidly against rotation by the torque bar extending from the machine quill or table? Machine torque bar must be stronger than the largest tap to be used.
 - 10. Is the proper cutting fluid or coolant being used for lubricating the tap?
 - 11. If a bottom hole is being tapped is there sufficient chip clearance?
 - 12. Is the correct Tapmatic model for the specific job requirement being used? (Capacity should be reduced 25% for roll form taps.)
 - 13. If a torque control attachment is being used, is the torque set correctly so tap will not break if accidentally bottomed?
 - 14. If depth control feature is employed, is it set correctly to cooperate with the machine stop, provide the total thread depth required and prevent engagement with bottom?
 - 15. Is machine retraction correct for tapping attachment being used?

References for this Safety Information include but are not limited to:

American National Standards Institute
ANSI B11.8-1983 (Adopted May 31, 1983
by Department of Defense)

Coastal Video Communications Corporation
Machine Guarding Copy Right 1994

Society Of Manufacturing Engineers
Tool and Manufacturing Engineers Handbook
Volume 1 Machining
(Library of Congress Catalog No. 82-060312)



30X, 50X, 70X, 90X Safety And Operation Instructions

This tapping attachment can be used on all types of manually operated machines with rotating non-reversing spindles. It can also be used in many applications that are automated or semi-automated, such as air feed drill units. It should not be used on machines which reverse the spindle on the back stroke or on machines which are automated and have no controlled back stroke.

MOUNTING THE STOP ARM:

This attachment incorporates in its design a planetary gear reverse which has a 1.75 to 1 reverse ratio. To assure the best performance of this reversing mechanism, it is extremely important that a short stop arm (as furnished with the unit) be employed. A truarc ring (#40X) is provided to hold the stop arm (#32X) in place. Extend strong torque bar from machine quill or machine table to engage short stop arm. **DO NOT LENGTHEN STOP ARM.** Also, clamp part to be tapped securely as full power of the machine is transmitted in reverse. **DO NOT HOLD PART BY HAND. DO NOT HOLD STOP ARM BY HAND.**


INSTALLING THE ARBOR IN TAPER MOUNT UNITS:

Make sure that the taper mount of the unit and the arbor itself are clean and free of oil or grease. Then with a twisting motion, insert the arbor into the tapping attachment. The twisting motion allows the air entrapped in the taper to be released. When the arbor is inserted completely, several sharp blows should be made on the tang with a lead hammer to make sure the arbor is seated firmly. It is important that this procedure be followed, as the taper may be damaged if slippage occurs. Occasionally, for large units, it may be necessary for the attachment to be pinned to the arbor. This may be done with a #4 Taper Pin.

INSERTING THE TAP:

Rubber flex Collet Spindle: If the tap you are using has a male center as in Figure 1, the point should be ground off so that the tap square will be engaged by the back jaws as shown in Figure 2.

After removing the point, insert the tap into the tap chuck of the attachment so that the back jaws will engage the square of the tap. Hand tighten the chuck nut first. Then tighten back jaws with hex key. Then using wrenches provided, tighten chuck nut. This procedure will assure true running of the tap. Note: Reduce capacity 25% for roll form taps.



TAPPING SPEEDS: The Tapping Attachment has been designed to operate properly at recommended tapping speeds. Please refer to chart for the recommendations for specific tap sizes. **Do not exceed the maximum speed shown on the tapping attachment.**

SETTING THE PRE-SELECTED TORQUE CONTROL:

The attachment has a spring loaded friction clutch. Driving adjustments are made by tightening or loosening the knurled torque cap (#2) at the upper end of the attachment.

To begin the tapping operations, set the clutch adjustment cap (#2) at a setting less than the final setting, then progressively tighten until the unit will

drive a sharp tap to the desired depth. When the desired torque has been determined, the knurled cap may be friction locked in place by a set screw (#5). If later during the operation the clutch slips, it is evident that the tap is dull and should be immediately exchanged for a sharp tap, but the clutch should not be tightened further.

The graduations on the housing are simply reference points, they do not refer to specific tap sizes. When the proper torque is determined for a specific job, this reference point may be noted to save set up time in the future.

THROUGH HOLE TAPPING: Tapping with this attachment does not require that the operator apply any lead pressure on the tap during the tapping operation. The free axial float in the attachment will automatically permit the tap to follow its own lead. The operator merely moves the machine's spindle behind the lead of the tap until the desired depth is reached. To reduce wear within the taper it is recommended that a short, quick, upward movement of the machine spindle be made during transition from drive to reverse. The tap will return to a forward rotation as soon as it rotates out of the hole.

BOTTOM HOLE TAPPING: For accurate and efficient bottom hole tapping, a machine feed stop should be used to allow the attachment's spindle to disengage in neutral before the tap bottoms in the hole. To achieve this, set the machine stop so that the machine feed plus the attachment's self-feed will equal the desired thread depth. This greatly simplifies the tapping operation, and affords maximum tap protection.

The amount of self-feed built into each of the tappers is as follows: M6 or 1/4" capacity is .140, M12 or 1/2" capacity is .250, M16 or 5/8" capacity is 3/8", M28 or 1 1/8" capacity is 1/2".

If the clutch should slip before the tap reaches the thread depth, check to see that the hole is the correct size, not packed with chips, and that the tap is sharp and undamaged. The torque control is designed as a safety device to prevent tap breakage in case the tap accidentally engages bottom. We do not recommend using the clutch for repetitive bottom hole tapping unless absolutely necessary.

LUBRICATION: This unit is pre-packed at the factory and only needs periodic additions of grease to maintain proper lubrication. Approximately every 600 hours, partially disassemble the unit, per disassembly instructions #1 through #11, and clean removed parts in solvent. Add a small amount (from 1/4 to 3/4 ounce) of #2 multipurpose lithium grease to reversing gears and reassemble. Do not over-lubricate- excess grease will create internal friction and overheating.

LUBRICATION: To insure maximum tap life, the proper lubricant should be used. We recommend Dry-Cut from MQL Systems A Division of Tapmatic. Call For FREE Sample.


REMOVAL OF TAPERED ARBORS: Removal of the arbor from the Jacobs taper in a tapping attachment will generally require striking the arbor with a soft metal rod. Hold the tapping attachment, with the arbor pointed away, in one hand and strike the arbor sideways on tang or in relief area, with a brass rod grasped in the other hand. Numerous blows may be required. **DO NOT STRIKE THE TAPPING ATTACHMENT.** Stubborn arbors and arbors installed with Loctite will require the application of heat. Using a soft flame propane torch, evenly heat the interface area where the arbor enters the attachment. (300% F will be required to break down the Loctite.) After applying heat, resume striking the arbor with the soft metal rod until the arbor loosens. Always use caution when handling heated parts.

MAXIMUM TAPMATIC TAPPING SPEEDS**

| Size | Cast Iron and Bronze | Plastics and Aluminum | Steel | Stainless Steel | Brass | Copper | Size | Cast Iron and Bronze | Plastics and Aluminum | Steel | Stainless Steel | Brass | Copper | |
|------|----------------------|-----------------------|-------|-----------------|-------|--------|------|----------------------|-----------------------|-------|-----------------|-------|--------|------|
| 0 | -80 | 2000 | 2000 | 2000 | 1900 | 2000 | 1/4 | -20 | 1000 | 1200 | 750 | 400 | 1200 | 1200 |
| 1 | -64 | 2000 | 2000 | 2000 | 1600 | 2000 | 1/4 | -28 | 1200 | 1200 | 850 | 400 | 1300 | 1200 |
| 1 | -72 | 2000 | 2000 | 2000 | 1600 | 2000 | 5/16 | -18 | 850 | 1100 | 650 | 300 | 1200 | 1100 |
| 2 | -56 | 1900 | 2000 | 1800 | 1300 | 2000 | 5/16 | -24 | 900 | 1200 | 700 | 350 | 1300 | 1200 |
| 2 | -64 | 2000 | 2000 | 1900 | 1300 | 2000 | 3/8 | -16 | 700 | 900 | 550 | 250 | 1200 | 900 |
| 3 | -48 | 1800 | 1900 | 1700 | 1000 | 1900 | 3/8 | -24 | 750 | 1000 | 600 | 300 | 1200 | 1000 |
| 3 | -56 | 1900 | 2000 | 1800 | 1100 | 2000 | 7/16 | -14 | 600 | 800 | 450 | 200 | 950 | 800 |
| 4 | -40 | 1700 | 1800 | 1500 | 900 | 1900 | 7/16 | -20 | 650 | 850 | 475 | 225 | 1000 | 850 |
| 4 | -48 | 1800 | 1900 | 1600 | 1000 | 2000 | 1/2 | -13 | 500 | 650 | 400 | 200 | 850 | 650 |
| 5 | -40 | 1650 | 1700 | 1600 | 800 | 1800 | 1/2 | -20 | 575 | 750 | 425 | 200 | 1000 | 750 |
| 5 | -44 | 1750 | 1800 | 1700 | 900 | 1900 | 9/16 | -12 | 450 | 600 | 350 | 175 | 800 | 600 |
| 6 | -32 | 1500 | 1600 | 1500 | 700 | 1700 | 9/16 | -18 | 500 | 675 | 375 | 175 | 900 | 675 |
| 6 | -40 | 1650 | 1700 | 1600 | 800 | 1800 | 5/8 | -11 | 375 | 500 | 300 | 150 | 700 | 500 |
| 8 | -32 | 1400 | 1400 | 1200 | 600 | 1400 | 5/8 | -18 | 450 | 600 | 325 | 150 | 800 | 600 |
| 8 | -36 | 1500 | 1500 | 1300 | 700 | 1500 | 3/4 | -10 | 325 | 400 | 250 | 125 | 575 | 400 |
| 10 | -24 | 1300 | 1400 | 1100 | 500 | 1500 | 3/4 | -16 | 375 | 475 | 275 | 125 | 650 | 450 |
| 10 | -32 | 1400 | 1500 | 1200 | 600 | 1500 | 7/8 | -9 | 275 | 350 | 200 | 90 | 500 | 350 |
| 12 | -24 | 1300 | 1400 | 900 | 400 | 1500 | 7/8 | -14 | 300 | 400 | 250 | 100 | 550 | 400 |
| 12 | -28 | 1400 | 1500 | 1000 | 500 | 1500 | 1 | -8 | 250 | 300 | 175 | 75 | 425 | 300 |
| | | | | | | | 1 | -14 | 275 | 350 | 200 | 100 | 475 | 350 |

**These maximum tapping speeds are for optimum tapping conditions for the tap size, tap pitch and material involved. Optimum conditions are (1) a through hole or blind hole with generous chip clearance; (2) thread depth is one times a tap diameter or less; (3) free machining material; (4) tap drill diameter for 60% thread; (5) use of LPS Tapmatic Cutting Fluid or Coolant; and (6) proper designed tap. Reduce speed accordingly for each non-optimum condition.

30X, 50X, 70X, 90X Parts Listing



| 30X Wrench Set | | | 50X Wrench Set | | | 70X Wrench Set | | | 90X Wrench Set | | |
|----------------|-----------|---|----------------|-----------|---|----------------|-----------|---|----------------|-----------|--------------------|
| Qty. | Order No. | Description | Qty. | Order No. | Description | Qty. | Order No. | Description | Qty. | Order No. | Description |
| 1 | 50332 | 332X Stop Arm | 1 | 56532 | 5032XB Stop Arm | 1 | 50732 | 732X Stop Arm | 1 | 50932 | 932X Stop Arm |
| 1 | 50340 | 340X Stop Arm Ring | 1 | 56540 | 5040XB Stop Arm Ring | 1 | 50740 | 740X Stop Arm Ring | 1 | 50940 | 940X Stop Arm Ring |
| 1 | 27078 | 5/64" Hex Key | 1 | 28075 | 3/4" Wrench | 1 | 27078 | 5/64" Hex Key | 1 | 27078 | 5/64" Hex Key |
| 1 | 28050 | 1/2" Wrench | 1 | 28097 | 31/32" Wrench | 1 | 27156 | 5/32" Hex Key | 1 | 27093 | 3/32" Hex Key |
| 1 | 28062 | 5/8" Wrench | 1 | 27125 | 1/8" Hex Key | 1 | 28097 | 31/32" Wrench | 1 | 27218 | 7/32" Hex Key |
| 1 | 29030 | 30 Series Spanner Wrench (Thread Mounts Only) | 1 | 27078 | 5/64" Hex Key | 1 | 28131 | 1 5/16" Wrench | 1 | 28156 | 1 9/16" Wrench |
| | | | 1 | 29050 | 50 Series Spanner Wrench (Thread Mounts Only) | 1 | 29085 | #5 Hook | 1 | 28200 | 2" Wrench |
| | | | | | | 1 | 29090 | Spring Puller | 1 | 29081 | #1 Hook |
| | | | | | | 1 | 29070 | 70 Series Spanner Wrench (Thread Mounts Only) | 1 | 29090 | Spring Puller |

30X, 50X, 70X, 90X Parts Listing

| IDENT | PART NAME | 30X | 50X | 70X | 90X |
|---------------|-------------------------------|-----------------|----------------|----------------|---------------|
| 1X (#6JT) | Housing | 50301B (1) | 50501B (1) | - | - |
| 1X (DINB16) | Housing | 50301G (1) | 50501G (1) | - | - |
| 1X (#33JT) | Housing | 50301E (1) | 50501E (1) | - | - |
| 1X (DINB12) | Housing | 50301F (1) | - | - | - |
| 1X (5/16"-24) | Housing | 50301H (1) | - | - | - |
| 1X (3/8"-24) | Housing | 50301I (1) | 50501I (1) | - | - |
| 1X (1/2"-20) | Housing | 50301J (1) | 50501J (1) | 50701J (1) | - |
| 1X (5/8"-16) | Housing | 50301K (1) | 50501K (1) | 50701K (1) | - |
| 1X (3/4"-16) | Housing | 50301L (1) | 50501L (1) | 50701L (1) | - |
| 1X (7/8"-20) | Housing | - | - | 50701M (1) | - |
| 1X (#3JT) | Housing | - | - | 50701C (1) | - |
| 1X (#4JT) | Housing | - | - | - | 50901D (1) |
| 1X(1 1/2"-18) | Housing | - | - | - | 50901N (1) |
| 2X | Clutch Adjustment Cap | 50302A (2) | 56502A (2) | 50702A (2) | 50902A (2) |
| 3X | Spring Plate | 50303 | 56503 | 50703 | 50903 |
| 4X | Driver Pins | 50304 (3 set) | 50704 (3 set) | 50704 (3 set) | 50904 (3 set) |
| 5X | Lock Set Screw | 50305A (3) | 50305A (3) | 50305A (3) | 50905A (3) |
| 5XX | Lock Set Screw Plug | 503051 | 503051 | 503051 | 509051 |
| 6X | Guide Spindle | 503061 | 56506 | 51720 | 51920 |
| 6XX | Upper Spring Hanger | - | - | 60334 | 50706 |
| 7X | Clutch Sleeve | 50307 | 50507 | 50707 | 50907 |
| 8X | Clutch Bearing | 50308 | 56508 | 50708 | 50908 |
| 9X | Gear Carrier Bearing (Ball) | - | 50509 | 50709 | 50909 |
| 9XA | Gear Carrier Bearing (Nylon) | 503091 | - | - | - |
| 9XX | Truarc Ring | - | 505091 | 507091 | 509091 |
| 11X | Retaining Ring | 50311 | 50511 | 50711 | 50911 |
| 11XX | Gear Washer | 503111 | 505111 | 507111 | 509111 |
| 12XA | Reversing Sleeve | 503121 (4) | 505121 (4) | 507121 (4) | 509121 (4) |
| 12XA1 | *Reversing Driver Spring | 51312 | 505122 | 507122 | 509122 |
| 13X | Gear Carrier | 503131 | 50513 | 50713 | 50913 |
| 14X | Drive Spindle | 503141A (5) | 56514A (5) | 50714A (5) | 50914A (5) |
| 15X | Back Jaw Retainer Screw | 50315 (2 req'd) | 50315 | 50715 | 50915 |
| 16X | *Back Jaws or Tap Jaws | 503161 | 56516 | 50716 | 50916 |
| 17X | Rubber Flex Collet (Small) | 21600 | 22100 | 24100 | 26100 |
| 17XX | Rubber Flex Collet (Large) | 21700 | 22200 | 24000 | 26200 |
| 18X | Tap Chuck Nut | 50318 | 56518 | 50718 | 50918 |
| 19X | Key | 50319 | 50319 | 50719 | 50919 |
| 20X | Stop Ring | 50320 | 56520 | 50720 | 50920 |
| 21X | Adjustment Thrust Bearing | - | 56521 | 50721 | 50921 |
| 22X | Clutch Spring (Large) | 50322 (3 set) | 50522 (9 set) | 50722 (9 set) | 50922 (9 set) |
| 23X | Clutch Spring (Small) | 50323 (3set) | 50723 (9set) | 50723 (9set) | 50923 (9 set) |
| 26X | *Cushion Spring | 50326 | 565261 | 50726 | 50926 |
| 27X | *Spring Cup Driver | 503271 | 505271 | 507271 | 50927 |
| 27XA | *Reversing Driver | 503272 | 505272 | 507272 | 509271 |
| 28X | Drive Pins | 50328 (3set) | 56528 (3 set) | 50728 (3 set) | 50928 (3 set) |
| 29X | Guide Spindle Bearing | 50329 | 56529 | 50729 | 51908 |
| 30X | *Return Spring | 51328 | 51528 | 507301 | 50930 |
| 31X | Drive Spindle Bearing | 503311 (4) | - (4) | - (4) | 509311 (4) |
| 32X | *Stop Arm | 50332 | 56532 | 50732 | 50932 |
| 33X | Guide Spindle Washer | 50333 | - | - | - |
| 34X | Guide Spindle Nut | 503341 | 56534 | - | - |
| 34XA | Spring Bearing | - | - | 50734 | 50934 |
| 34XX | Spring Bearing Hanger | - | - | 50706 | 50706 |
| 35X | Ring Gear | 50335 | 50535 | 50735 | 50935 |
| 36X | Gear Pins | 50336 (3 set) | 50536 (3 set) | 50736 (3 set) | 50936 (3 set) |
| 37X | Planet Gears | 50337 (3 set) | 50537 (3 set) | 50737 (3 set) | 50937 (3 set) |
| 38X | Spacer | 50338 | 50538 | 50738 | 50938 |
| 39X | Thrust Washer | 50339 | 50539 | 50739 | 50939 |
| 40X | Truarc Ring | 50340 | 56540 | 50740 | 50940 |
| 41X | Clutch Driver | 50341 | 56541 | 50741 | 50941 |
| 42X | Primary Internal Clutch Plate | 50342 | 56542 | 50742 | 50942 |
| 42XX | Internal Clutch Plate | 503421 | 565421 (2 set) | 507421 (2 set) | 509421 (3set) |
| 43X | External Clutch Plate | 50343 | 56543 (2 set) | 50743 (2 set) | 50943 (3 set) |
| 44X | *Clutch Discs | 50344 (3 set) | 56544 (5 set) | 50744 (5 set) | 50944 (7 set) |
| 46XA | Reversing Sleeve Bushing | 503461 | 505461 | 507461 | 509461 |

*These items are considered normal wear replacement parts and are not covered under warranty.
 (1) Housing only available as an assembly with Ident. #4X and #6X.
 (2) Clutch Adjustment Cap only available as an assembly with Ident #5X and #5XX.
 (3) Lock Set Screw comes with Ident. #5XX.

(4) Reversing Sleeve and Drive Spindle Bearing available only as an assembly.
 (5) Drive Spindle only available as an assembly with Ident. #29X.

INSTRUCTIONS FOR DISASSEMBLY

- Remove stop ring (#20X) and unscrew clutch adjustment cap (#2X).
- Hold unit in vertical position and remove adjustment thrust bearing (#21X). (50X, 70X & 90X only).
- Lift off spring plate (#3X).
- Carefully invert unit over a clean receptacle. Clutch springs (#22X & 23X) will drop out.
- Remove tap chuck nut (#18X) and collet (#17X).
- Remove back jaw retainer screw (#15X).
- Remove back jaw (#16X).
- Remove return spring (#30X) by threading spring puller (supplied with unit) into tapped hole in part (#34XX), and pulling out to expose spring for removal with spring hook (also supplied with unit). (Models 70X and 90X only).
- Unscrew guide spindle nut (#34X) and remove return spring (#30X). (Models 30X & 50X).
- Remove truarc ring (#40X) and stop arm (#32X).
- Remove truarc ring (#11X) and gear washer (#11XX).
- Lift out drive spindle (#14X) and reversing sleeve (#12XA) sub assembly from unit.
- Lift out spacers (#46XA) and (#38X).
- Lift out clutch sleeve (#7X), clutch driver (#41X), clutch plates (#42X, 42XX, 43X) and clutch discs (#44X).
- Lift out cushion spring (#26X) and spring cup driver (#27X).
- Remove driver pins (#28X) from drive spindle (#14X).
- Press drive spindle (#14X) out of reversing sleeve (#12XA) subassembly.
- Do not disassemble planetary gear reversing subassembly (#13X).

INSTRUCTIONS FOR ASSEMBLY

- Clean and lubricate all parts requiring lubrication thoroughly. Do not get clutch parts wet or oily.
- Place internal clutch plate (#42X) on clutch sleeve (#7X), then clutch disc (#44X), then external clutch plate (#42X), then another clutch disc (#44X), then internal clutch

- plate (#42XX), and so forth, until you have all plates and discs on clutch sleeve, then line up external dogs so that you can slip clutch driver (#41X) over complete subassembly.
- Place cushion spring (#26X) and spring cup driver (#27X) in clutch sleeve (#7X).
- Insert clutch sleeve (#7X) and clutch driver (#41X) subassembly into housing (#1X), making sure that 3 holes in clutch driver mate with 3 pins in housing (#1X).
- Insert spacers (#46XA) and (#38X) into housing (#1X).
- Press drive spindle (#14X) into reversing sleeve (#12XA) subassembly and insert drive pins (#28X).
- Insert complete subassembly into housing (#1X) utilizing key (#19X).
- Insert gear washer (#11XX) and snap in truarc ring (#11X).
- Hook return spring (#30X) to spring hanger (#6X) and insert this subassembly into neck end of housing (#1X) making certain spring hanger is seated properly. (Models 70X and 90X only).
- Use spring hook (supplied with unit) to expose return spring (#30X) and attach spring bearing hanger (#34XX) with bearing (#34XA) mounted. (Models 70X and 90X).
- Thread spring puller (supplied with unit) into tapped hole in spring hanger (#34XX) and carefully lower assembly into drive spindle (#14X) until bearing (#34XA) seats itself, then unscrew spring puller. (Models 70X and 90X).
- Insert return spring (#30X) into drive spindle (#14X) and screw guide spindle nut on to guide spindle (#6X). (Models 30X and 50X).
- Place back jaws (#16X) in drive spindle (#14X) and install back jaw retainer screw (#15X).
- Insert collet (#17X) into tap chuck nut (#18X) and screw tap chuck nut (#18X) on to drive spindle (#14X).
- Insert clutch springs (#22X & 23X) into unit.
- Place spring plate (#3X) on springs.
- Place adjustment thrust bearing (#21X) on spring plate (#3X). Models 50X, 70X and 90X).
- Screw on clutch adjustment cap (#2X).
- Install stop ring (#20X).
- Install stop arm (#32X) and snap on truarc ring (#40X).



30X, 50X, 70X, 90X Repair Service

Repair Service is available at...

Attention: Repair Department
Tapmatic Corporation
802 Clearwater Loop
Post Falls, ID 83854

To Expedite Repair: Return tool direct to Tapmatic Corporation, by United Parcel Service and enclose the following statement with your purchase order: **"Authorization given to repair and return tool without notification if total repair cost does not exceed 40% of the cost of a new tool."** Tapmatic will repair the tool and call to request your credit card # for invoicing.

IMPORTANT: Be sure to return the tool complete with the tap chuck nut, back jaw and if the tool is a reversing unit, include stop arm. Otherwise, we will add these missing parts to every non-warranty repair.

Cost Notification: Tapmatic will FAX a cost notification to you, soliciting your approval before repairs are completed.

If it is determined that a tapping attachment cannot be repaired, at the customer's request, Tapmatic will return the disassembled parts. We are not able to reassemble tapping attachments using damaged or worn out parts.

Optional Return Procedure: Tools may also be returned for repair through your local Tapmatic Distributor. They will ship the tool to us and include instructions for the repair and return. You may already have an open account with them which facilitates the handling of invoicing.

Priority Service: Tapmatic services tapping attachments returned for repair in the order in which they are received. All tools will be evaluated and repaired within three weeks from the date they arrive subject to receiving the customer's approval to proceed with the repair.

Priority is given to the tools shipped to us by overnight or second day.

If a repair is sent to us by UPS ground or similar service it can also be given priority. Just call and let us know you need priority service and advise if you would like the tool returned to you by overnight or second day. In the interest of fairness, to all our customers, we ask that you approve return shipment by overnight or second day before we agree to upgrade your repair order to priority service. Typical turnaround, not including shipping time, for priority repairs is 3 days subject to receiving the customer's approval to proceed with the repair.

If we can answer any questions, please call our toll free number: 800 395-8231.



The Tapping Specialists

TAPMATIC CORPORATION: ISO 9001 CERTIFIED
802 Clearwater Loop, Post Falls, Idaho 83854
Phone: (208) 773-8048, (800) 854-6019, FAX: (208) 773-3021

TAPMATIC INTERNATIONAL CORPORATION
Alte Rheinstrasse, CH-9451 Kriessern, Switzerland
Phone: 011 41 71 757 5900, FAX: 011 41 71 757 5901



Distributed By: